



Item Change – Air Top 2000 Power/Switch Harness

01-20-2002

Starting the last quarter of year 2001, all Air Top 2000 Power/Switch harnesses were redesigned to omit the diagnostic link. A new Item is now available to take the place of the diagnostic link which was previously part of the harness.

For Webasto service facilities and end-users utilizing the PC diagnostic capabilities of the Air Top 2000 heater, the NEW adapter (pigtail) is required to allow communication between the heater and the diagnostic kit where the new power/switch harness is in use. The new adapter can be ordered under part number 5000007A.


Note: The new adapter (pigtail) is used in conjunction with the diagnostic adapter P/N 1319943A and the diagnostic kit P/N 1301728B.

As a cost savings, the new adapter AND the diagnostic adapter can be ordered together under part number 5000009A.


The new adapter (pigtail) is inserted into position 5 of the X1 connector that plugs into the control circuit board. Once installed, the diagnostic kit can be connected in the usual manner as before, using the appropriate diagnostic adapter (P/N 1319943A) included in the PC Diagnostic kit.

No changes are required to your existing PC Diagnostic kit or to the software and appropriate adapter.

Note: Diagnostic adapters for heaters other than the Air Top 2000 and Thermo Top Z/C are not included in the PC Diagnostic kit and must be ordered separately. For a listing of all available diagnostic adapters, contact your Webasto representative or call Webasto Thermosystems directly.



New Adapter (Pigtail) P/N 5000007A



Diagnostic Adapter P/N 1319943A

The above items illustrated can be ordered separately or together as a kit under part number 5000009A.