

Air Top 3500/5000 Burner Replacement Kit


08-10-2000 rev. 5/2015

Improved Burner Chamber and Burner Tube for the Air Top 3500 / 5000 Heaters

A manufacturing change to the Air Top 3500 and Air Top 5000 burner chamber and burner tube begins 12/99. This enhancement reduces the thermal load on the ceramic igniter effectively increasing the life span of the igniter.

Due to good product reliability to date, it is not necessary to replace burner chambers and burner tubes in units currently in service, however, when heaters are serviced, they can be brought up to the new standard.

To perform this modification, it is necessary to replace the burner chamber and burner tube. For this purpose, we have developed two burner upgrade kits, one for 12 volt units and one for 24 volt units.



Ordering Information

Upgrade parts for changing current (former) standard to the latest standard - AT 3500/5000.

12 Volt Upgraded Burner Kit	67984
24 Volt Upgraded Burner Kit	1322862
Workshop Repair Manual	63380