

## Category: Marine



Document Number: PI129BC




Date: 04/29/2016 Rev 8/15/2018

Description: **General Maintenance for Webasto 40 Series Marine Sunroof**



**WARNING:** Cancer and Reproductive Harm  
[www.P65Warnings.ca.gov](http://www.P65Warnings.ca.gov)

### Maintenance

Procedure		Frequency
<p>Clean the roof and tracks regularly.</p> <ul style="list-style-type: none"> <li>- Wash the glass panel with clean water and a soft cloth, chamois, or sponge.</li> <li>- Never rub a dry surface. Do <b>not</b> use abrasive or harsh solutions such as turpentine or mineral spirits when cleaning glass panels.</li> <li>- Wash the remainder of the roof with warm water using a professional marine grade cleaning product. Rinse with clean water.</li> </ul>		<p>Monthly</p>
<p>Apply a thin layer of grease (Isoflex® Topas L32) to the inside of the rails (A) and guides (H) to ensure smooth sliding. Available through Webasto.</p> <p>Never Use:</p> <ul style="list-style-type: none"> <li>- Alkaline products containing sodium solutions;</li> <li>- Acid products like muriatic or those containing phosphor; Steel wool, abrasives or sandpaper;</li> <li>- Cleaning products for glass containing alkaline, which can corrode aluminum.</li> </ul>		<p>Annually</p>
<p>Check all electrical connections for corrosion. If corrosion is discovered consult your local dealer for necessary repairs.</p>		<p>Annually</p>

If you have any questions, contact our technical support team at (800) 860-7866 or via email at: [info-us@webasto.com](mailto:info-us@webasto.com).